

APPENDIX A

FORMOSA PLASTICS CORPORATION Point Comfort, Texas

Photographs from June 16, 2010 Inspection

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY


Official Photograph Log
Photo No. 1



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 9:16:00 AM
City/County: Point Comfort, Calhoun	Direction (facing): Down	State: TX
Location: Formosa Plastics Corp.		
Subject: LLDPE Bagging Area - Floor sweep pellets stored in box		
Photo ID: DSCF3328		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 2



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 9:16:00 AM
City/County: Point Comfort, Calhoun	Direction (facing): North	State: TX
Location: Formosa Plastics Corp		
Subject: LLDPE Bagging Area - explaining process to Frances Verhalen, EPA R6 6EN inspector		
Photo ID: DSCF3329		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 3



Photographer: Nancy Fagan	Date: 6/16/2000	Time: 9:20:00 AM
City/County: Point Comfort/Calhoun	Direction (facing): West	State: TX
Location: Formosa Plastics Corporation		
Subject: LLDPE Bagging Area - FPC workers at bagging process line		
Photo ID: DSCF3330		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 4



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 9:25:00 AM
City/County: Point Comfort/Calhoun	Direction (facing): Up	State: TX
Location: Formosa Plastics Corporation		
Subject: LLDPE Bagging Area - Silos to LLDPE		
Photo ID: DSCF3331		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 5



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 9:29:00 AM
City/County: Point Comfort/Calhoun	Direction (facing): Down	State: TX
Location: Formosa Plastics Corporation		
Subject: LLDPE Railcar Loading Area - Hopper of scrap LLDPE inside railcar loading area		
Photo ID: DSCF3332		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 6



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 9:33:00 AM
City/County: Point Comfort, Calhoun	Direction (facing): North	State: TX
Location: Formosa Plastics Corp.		
Subject: LLDPE Railcar Loading Area - LLDPE pellets on concrete		
Photo ID: DSCF3333		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY


Official Photograph Log
Photo No. 7



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 9:34:00 AM
City/County: Point Comfort, Calhoun	Direction (facing): West	State: TX
Location: Formosa Plastics Corp.		
Subject: LLDPE Railcar Loading Area - LLDPE pellets on traintrack loading area		
Photo ID: DSCF3334		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 8



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 9:48:00 AM
City/County: Point Comfort, Calhoun	Direction (facing): North	State: TX
Location: Formosa Plastics Corp.		
Subject: PVC Plant - Drainage ditch; sign posted "Cancer suspect agent area Authorized Personnel Only" (with Photo 9)		
Photo ID: DSCF3335		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 9



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 9:48:00 AM
City/County: Point Comfort, Calhoun	Direction (facing): Northwest	State: TX
Location: Formosa Plastics Corp.		
Subject: PVC Plant - Drainage ditch; Employee washing down drainage ditch (with Photo 8)		
Photo ID: DSCF3336		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 10



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 9:51:00 AM
City/County: Point Comfort, Calhoun	Direction (facing): North	State: TX
Location: Formosa Plastics Corp.		
Subject: PVC Plant - One (1) ton bags of PVC product		
Photo ID: DSCF3337		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 11



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 9:52:00 AM
City/County: Point Comfort, Calhoun	Direction (facing): Northeast	State: TX
Location: Formosa Plastics Corp.		
Subject: PVC Plant - PVC dust in PVC plant parking lot and roadway; transformers in background		
Photo ID: DSCF3338		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 12



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 9:52:00 AM
City/County: Point Comfort, Calhoun	Direction (facing): Down	State: TX
Location: Formosa Plastics Corp.		
Subject: PVC Plant - Storm drain culvert		
Photo ID: DSCF3339		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY


Official Photograph Log
Photo No. 13



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 9:54:00 AM
City/County: Point Comfort, Calhoun	Direction (facing): North	State: TX
Location: Formosa Plastics Corp.		
Subject: PVC Plant - Storm drainage in PVC plant with piles of PVC in drainage channel		
Photo ID: DSCF3340		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 14



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 9:54:00 AM
City/County: Point Comfort, Calhoun	Direction (facing): Down	State: TX
Location: Formosa Plastics Corp.		
Subject: PVC Plant - Storm drainage in PVC plant with piles of PVC in drainage channel		
Photo ID: DSCF3341		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 15



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 10:04:00 AM
City/County: Point Comfort, Calhoun	Direction (facing): Down	State: TX
Location: Formosa Plastics Corp.		
Subject: PVC Plant - Storm grate in PVC plant		
Photo ID: DSCF3342		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 16



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 10:04:00 AM
City/County: Point Comfort, Calhoun	Direction (facing): Down	State: TX
Location: Formosa Plastics Corp.		
Subject: PVC Plant - Storm grate in PVC plant; apparent PVC dust in drainage channel		
Photo ID: DSCF3343		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 17



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 10:07:00 AM
City/County: Point Comfort, Calhoun	Direction (facing): South	State: TX
Location: Formosa Plastics Corp.		
Subject: PVC Plant - PVC reactors; gray trash cans marked "Scale Only"		
Photo ID: DSCF3344		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY


Official Photograph Log
Photo No. 18



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 10:10:00 AM
City/County: Point Comfort, Calhoun	Direction (facing): Southwest	State: TX
Location: Formosa Plastics Corp.		
Subject: PVC Plant - PVC scrubber area; Steam trap with PVC dust on ground (with Photo 19)		
Photo ID: DSCF3345		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 19



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 10:10:00 AM
City/County: Point Comfort, Calhoun	Direction (facing): Down	State: TX
Location: Formosa Plastics Corp.		
Subject: PVC Plant - PVC scrubber area; Steam trap with PVC dust on ground (with Photo 18)		
Photo ID: DSCF3346		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 20



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 10:14:00 AM
City/County: Point Comfort, Calhoun	Direction (facing): Down	State: TX
Location: Formosa Plastics Corp.		
Subject: PVC Plant - PVC settling pit and overflow area		
Photo ID: DSCF3347		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 21



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 10:18:00 AM
City/County: Point Comfort, Calhoun	Direction (facing): East	State: TX
Location: Formosa Plastics Corp.		
Subject: PVC Plant - PVC settling pit with one (1) ton bags of settling pit sludge marked PTC 06 staged adjacent to pit; overflow on concrete area adjacent to storm drainage channel		
Photo ID: DSCF3348		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 22



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 10:19:00 AM
City/County: Point Comfort, Calhoun	Direction (facing): Northeast	State: TX
Location: Formosa Plastics Corp.		
Subject: PVC Plant - One (1) ton bags of settling pit sludge marked PTC 06 staged adjacent to pit		
Photo ID: DSCF3349		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 23



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 10:25:00 AM
City/County: Point Comfort, Calhoun	Direction (facing): Southwest	State: TX
Location: Formosa Plastics Corp.		
Subject: PVC Plant - PVC silos		
Photo ID: DSCF3350		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 24



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 11:16:00 AM
City/County: Point Comfort, Calhoun	Direction (facing): Southwest	State: TX
Location: Formosa Plastics Corp.		
Subject: 90 Day Hazardous Waste Storage Yard - Roll-off boxes of soil and debris; non-hazardous waste boxes stored on hazardous waste pad		
Photo ID: DSCF3351		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 25



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 11:39:00 AM
City/County: Point Comfort, Calhoun	Direction (facing): Up	State: TX
Location: Formosa Plastics Corp.		
Subject: Combined WWTP - Tank TTT-44, with apparent rust stains (with Photo 26)		
Photo ID: DSCF3352		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 26



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 11:39:00 AM
City/County: Point Comfort, Calhoun	Direction (facing): Up	State: TX
Location: Formosa Plastics Corp.		
Subject: Combined WWTP - Tank TTT-44, with apparent rust stains (with Photo 25)		
Photo ID: DSCF3353		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 27



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 11:41:00 AM
City/County: Point Comfort, Calhoun	Direction (facing): Northwest	State: TX
Location: Formosa Plastics Corp.		
Subject: Combined WWTP - Overflow discharged onto concrete pad from cooling tower associated with chlor-alkali plant (see Photo 28)		
Photo ID: DSCF3354		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 28



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 11:42:00 AM
City/County: Point Comfort, Calhoun	Direction (facing): West	State: TX
Location: Formosa Plastics Corp.		
Subject: Combined WWTP - Overflow originating from overflow from cooling tower associated with chlor-alkali plant (see Photo 27)		
Photo ID: DSCF3355		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY


Official Photograph Log
Photo No. 29



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 11:42:00 AM
City/County: Point Comfort, Calhoun	Direction (facing): West	State: TX
Location: Formosa Plastics Corp.		
Subject: Central WWTP - Apparent corrosion on vanes of cooling tower associated with chlor-alkali plant		
Photo ID: DSCF3356		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 30



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 11:54:00 AM
City/County: Point Comfort, Calhoun	Direction (facing): Northwest	State: TX
Location: Formosa Plastics Corp.		
Subject: Central WWTP - Out-of-service tank down for cleaning of sludges (approximately 3 feet deep) from tank bottom (TTT-08A)		
Photo ID: DSCF3357		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 31



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 11:58:00 AM
City/County: Point Comfort, Calhoun	Direction (facing): West	State: TX
Location: Formosa Plastics Corp.		
Subject: Central WWTP - Apparent corrosion of pumps and appurtenances in CWWTP area		
Photo ID: DSCF3358		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 32



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 12:00:00 PM
City/County: Point Comfort, Calhoun	Direction (facing): Down	State: TX
Location: Formosa Plastics Corp.		
Subject: Central WWTP – Water decant pipe with sludge flowing into north storm water drainage channel that flows back into the CWWTP system		
Photo ID: DSCF3359		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 33



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 12:03:00 PM
City/County: Point Comfort, Calhoun	Direction (facing): Northwest	State: TX
Location: Formosa Plastics Corp.		
Subject: Central WWTP - Pretreatment area (influent piping)		
Photo ID: DSCF3360		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 34



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 12:07:00 PM
City/County: Point Comfort, Calhoun	Direction (facing): Southeast	State: TX
Location: Formosa Plastics Corp.		
Subject: Central WWTP - New tank being installed		
Photo ID: DSCF3361		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 35



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 12:07:00 PM
City/County: Point Comfort, Calhoun	Direction (facing): West	State: TX
Location: Formosa Plastics Corp.		
Subject: Central WWTP - TTT-02 tank in foreground; part of biological pretreatment area		
Photo ID: DSCF3362		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 36



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 12:10:00 PM
City/County: Point Comfort, Calhoun	Direction (facing): Southeast	State: TX
Location: Formosa Plastics Corp.		
Subject: Central WWTP - View of new Tank TTT-01A and Tank TTT-02 (panorama with Photos 37 and 38)		
Photo ID: DSCF3363		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log

Photo No. 37



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 12:10:00 PM
City/County: Point Comfort, Calhoun	Direction (facing): South	State: TX
Location: Formosa Plastics Corp.		
Subject: Central WWTP - View of Tank TTT-02 (panoraph with Photos 36 and 38)		
Photo ID: DSCF3364		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 38



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 12:10:00 PM
City/County: Point Comfort, Calhoun	Direction (facing): Southwest	State: TX
Location: Formosa Plastics Corp.		
Subject: Central WWTP - View of Tank TTT-01A and Tank TTT-02 (panorama with Photos 36 and 37)		
Photo ID: DSCF3365		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 39



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 12:10:00 PM
City/County: Point Comfort, Calhoun	Direction (facing): West	State: TX
Location: Formosa Plastics Corp.		
Subject: Central WWTP - Process area showing distressed vegetation; north of TTT-01A and TTT-02 (According to FPC personnel, vegetation controlled with commercial herbicide)		
Photo ID: DSCF3366		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 40



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 12:14:00 PM
City/County: Point Comfort, Calhoun	Direction (facing): East	State: TX
Location: Formosa Plastics Corp.		
Subject: Central WWTP - Storm water piping, sump, and pumps at CWWTP		
Photo ID: DSCF3367		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 41



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 12:15:00 PM
City/County: Point Comfort, Calhoun	Direction (facing): Northeast	State: TX
Location: Formosa Plastics Corp.		
Subject: Central WWTP - Roll-off container of sludge covered with black tarp (Verhalen - EPA and - FPC in photo)		
Photo ID: DSCF3368		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY


Official Photograph Log
Photo No. 42



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 12:20:00 PM
City/County: Point Comfort, Calhoun	Direction (facing): Down	State: TX
Location: Formosa Plastics Corp.		
Subject: Central WWTP - Drainage from roll-off box of sludge from CWWTP prior to off-site disposal of sludge in Class 2 landfill		
Photo ID: DSCF3369		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 43



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 12:25:00 PM
City/County: Point Comfort, Calhoun	Direction (facing): Southwest	State: TX
Location: Formosa Plastics Corp.		
Subject: Central WWTP - Pumps located adjacent to corrosive storm water drainage area		
Photo ID: DSCF3370		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 44



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 12:26:00 PM
City/County: Point Comfort, Calhoun	Direction (facing): Up	State: TX
Location: Formosa Plastics Corp.		
Subject: Central WWTP - Bird nest on piping in CWWTP area		
Photo ID: DSCF3371		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 45



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 12:28:00 PM
City/County: Point Comfort, Calhoun	Direction (facing): South	State: TX
Location: Formosa Plastics Corp.		
Subject: Central WWTP – Biological aeration tank TTT-08C (see Photos 46 and 47)		
Photo ID: DSCF3372		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log

Photo No. 46



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 12:31:00 PM
City/County: Point Comfort, Calhoun	Direction (facing): Southwest	State: TX
Location: Formosa Plastics Corp.		
Subject: Central WWTP - Sludge handling tanks TTT-22, and TTT-30 (see Photos 45 and 47)		
Photo ID: DSCF3373		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 47



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 12:32:00 PM
City/County: Point Comfort, Calhoun	Direction (facing): Southwest	State: TX
Location: Formosa Plastics Corp.		
Subject: Central WWTP - Sludge handling tanks TTT-22, and TTT-30 (see Photos 45 and 46)		
Photo ID: DSCF3374		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 48



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 12:34:00 PM
City/County: Point Comfort, Calhoun	Direction (facing): Up	State: TX
Location: Formosa Plastics Corp.		
Subject: Central WWTP - Sludge drying process; sludges are dropped thorough a chute and stored in roll-off boxes (see Photos 49 and 50)		
Photo ID: DSCF3375		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 49



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 12:35:00 PM
City/County: Point Comfort, Calhoun	Direction (facing): Up	State: TX
Location: Formosa Plastics Corp.		
Subject: Central WWTP - Sludge drying process; sludges are dropped thorough a chute and stored in roll-off boxes (see Photos 48 and 50)		
Photo ID: DSCF3376		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 50



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 12:35:00 PM
City/County: Point Comfort, Calhoun	Direction (facing): Up	State: TX
Location: Formosa Plastics Corp.		
Subject: Central WWTP - Sludge drying process; sludges are dropped thorough a chute and stored in roll-off boxes (see Photos 48 and 49)		
Photo ID: DSCF3377		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 51



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 12:37:00 PM
City/County: Point Comfort, Calhoun	Direction (facing): West	State: TX
Location: Formosa Plastics Corp.		
Subject: Central WWTP - Dried sludge falling from belt of pressing machine		
Photo ID: DSCF3378		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 52



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 12:37:00 PM
City/County: Point Comfort, Calhoun	Direction (facing): Northwest	State: TX
Location: Formosa Plastics Corp.		
Subject: Central WWTP - TFT-02B sludge pressing machine		
Photo ID: DSCF3379		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 53



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 12:40:00 PM
City/County: Point Comfort, Calhoun	Direction (facing): Northwest	State: TX
Location: Formosa Plastics Corp.		
Subject: Central WWTP - Inside Chemical Storage Building - Product storage area (- FPC, Verhalen - EPA, and Phyllis Cunningham - TCEQ in picture)		
Photo ID: DSCF3380		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 54



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 12:41:00 PM
City/County: Point Comfort, Calhoun	Direction (facing): North	State: TX
Location: Formosa Plastics Corp.		
Subject: Central WWTP - Inside Chemical Storage Building -Flocculant container		
Photo ID: DSCF3381		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log

Photo No. 55



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 12:42:00 PM
City/County: Point Comfort, Calhoun	Direction (facing): Down	State: TX
Location: Formosa Plastics Corp.		
Subject: Central WWTP - Inside Chemical Storage Building -Label on flocculant container		
Photo ID: DSCF3382		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 56



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 12:43:00 PM
City/County: Point Comfort, Calhoun	Direction (facing): South	State: TX
Location: Formosa Plastics Corp.		
Subject: Central WWTP - Outside Chemical Storage Building -Drums of sodium bisulfite		
Photo ID: DSCF3383		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 57



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 12:47:00 PM
City/County: Point Comfort, Calhoun	Direction (facing): South	State: TX
Location: Formosa Plastics Corp.		
Subject: Central WWTP - Treated groundwater from VC-630A discharges into mixing basin for Outfalls 201 and 101.		
Photo ID: DSCF3384		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 58



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 12:52:00 PM
City/County: Point Comfort, Calhoun	Direction (facing): Southwest	State: TX
Location: Formosa Plastics Corp.		
Subject: Central WWTP - Mixing basin for Outfalls 201 and 101		
Photo ID: DSCF3385		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 59



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 1:58 PM
City/County: Point Comfort, Calhoun	Direction (facing): Southwest	State: TX
Location: Formosa Plastics Corp.		
Subject: Outfall 00? - Most likely outfall 003 but the number has eroded away; water up- and down-stream of the gate		
Photo ID: DSCF3386		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 60



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 2:02 PM
City/County: Point Comfort, Calhoun	Direction (facing): North	State: TX
Location: Formosa Plastics Corp.		
Subject: Chemical Storage Building in PVC area - Product storage		
Photo ID: DSCF3387		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log

Photo No. 61



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 2:02 PM
City/County: Point Comfort, Calhoun	Direction (facing): North	State: TX
Location: Formosa Plastics Corp.		
Subject: Chemical Storage Building in PVC area - Product storage, bagged material		
Photo ID: DSCF3388		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 62



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 2:03 PM
City/County: Point Comfort, Calhoun	Direction (facing): Northwest	State: TX
Location: Formosa Plastics Corp.		
Subject: Chemical Storage Building in PVC area - Product storage, materials in drums or totes		
Photo ID: DSCF3389		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 63



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 2:03 PM
City/County: Point Comfort, Calhoun	Direction (facing): North	State: TX
Location: Formosa Plastics Corp.		
Subject: Chemical Storage Building in PVC area - Product storage, drum labeled 'PC07 SAT Storage'		
Photo ID: DSCF3390		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 64



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 2:04 PM
City/County: Point Comfort, Calhoun	Direction (facing): Down	State: TX
Location: Formosa Plastics Corp.		
Subject: Chemical Storage Building in PVC area - Product storage, drum labeled 'Pationic AS-33'		
Photo ID: DSCF3391		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 65



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 2:04 PM
City/County: Point Comfort, Calhoun	Direction (facing): West	State: TX
Location: Formosa Plastics Corp.		
Subject: Chemical Storage Building in PVC area - Product storage, tote of apparently flammable materials		
Photo ID: DSCF3392		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 66



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 2:05 PM
City/County: Point Comfort, Calhoun	Direction (facing): Down	State: TX
Location: Formosa Plastics Corp.		
Subject: Chemical Storage Building in PVC area - Product storage, one (1) ton bag of product		
Photo ID: DSCF3393		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 67



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 2:06 PM
City/County: Point Comfort, Calhoun	Direction (facing): Northwest	State: TX
Location: Formosa Plastics Corp.		
Subject: Chemical Storage Building in PVC area - Product storage, mechanical parts storage area		
Photo ID: DSCF3394		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log

Photo No. 68



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 2:06 PM
City/County: Point Comfort, Calhoun	Direction (facing): North	State: TX
Location: Formosa Plastics Corp.		
Subject: Chemical Storage Building in PVC area - Product storage, Locked storage box containing office files		
Photo ID: DSCF3395		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 69



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 2:07 PM
City/County: Point Comfort, Calhoun	Direction (facing): North	State: TX
Location: Formosa Plastics Corp.		
Subject: Chemical Storage Building in PVC area - Product storage, Metal totes		
Photo ID: DSCF3396		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 70



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 2:08 PM
City/County: Point Comfort, Calhoun	Direction (facing): Up	State: TX
Location: Formosa Plastics Corp.		
Subject: Chemical Storage Building in PVC area - Product storage, Metal totes, close-up of label with 'ADDIOX 1016' on label		
Photo ID: DSCF3397		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 71



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 2:17 PM
City/County: Point Comfort, Calhoun	Direction (facing): Down	State: TX
Location: Formosa Plastics Corp.		
Subject: Outfall 002		
Photo ID: DSCF3398		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY


Official Photograph Log
Photo No. 72



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 2:18 PM
City/County: Point Comfort, Calhoun	Direction (facing): Down	State: TX
Location: Formosa Plastics Corp.		
Subject: Outfall 004 - gate closed (see Photo 73)		
Photo ID: DSCF3399		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 73



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 2:20 PM
City/County: Point Comfort, Calhoun	Direction (facing): Down	State: TX
Location: Formosa Plastics Corp.		
Subject: Outfall 004 - water very brown; apparent crack in headwall of outfall (see Photo 72)		
Photo ID: DSCF3400		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 74



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 2:21 PM
City/County: Point Comfort, Calhoun	Direction (facing): Southwest	State: TX
Location: Formosa Plastics Corp.		
Subject: Outfall 004 - water very brown (see Photos 75 and 76)		
Photo ID: DSCF3401		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 75



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 2:26 PM
City/County: Point Comfort, Calhoun	Direction (facing): Down	State: TX
Location: Formosa Plastics Corp.		
Subject: Outfall 005 - water present up- and down-stream from the gate (see Photos 74 and 76)		
Photo ID: DSCF3402		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 76



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 2:26 PM
City/County: Point Comfort, Calhoun	Direction (facing): Northwest	State: TX
Location: Formosa Plastics Corp.		
Subject: Outfall 005 - water present up- and down-stream from the gate (see Photos 74 and 75)		
Photo ID: DSCF3403		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 77



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 2:32 PM
City/County: Point Comfort, Calhoun	Direction (facing): Northwest	State: TX
Location: Formosa Plastics Corp.		
Subject: Outfall 006		
Photo ID: DSCF3404		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 78



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 2:32 PM
City/County: Point Comfort, Calhoun	Direction (facing): Down	State: TX
Location: Formosa Plastics Corp.		
Subject: Outfall 006 - plastic pellets found floating on water surface downstream of gate (see Photo 79)		
Photo ID: DSCF3405		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 79



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 2:33 PM
City/County: Point Comfort, Calhoun	Direction (facing): West	State: TX
Location: Formosa Plastics Corp.		
Subject: Outfall 006 - plastic pellets found floating on water surface downstream of gate (see Photo 78)		
Photo ID: DSCF3406		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 80



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 2:33 PM
City/County: Point Comfort, Calhoun	Direction (facing): Down	State: TX
Location: Formosa Plastics Corp.		
Subject: Outfall 006 - Close-up of plastic pellets found floating on water surface downstream of gate		
Photo ID: DSCF3407		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 81



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 2:34 PM
City/County: Point Comfort, Calhoun	Direction (facing): Down	State: TX
Location: Formosa Plastics Corp.		
Subject: Outfall 006 - Plastic pellets on concrete steps from earlier highwater event downstream of gate		
Photo ID: DSCF3408		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log

Photo No. 82

No Photograph

Photographer:	Date:	Time:
City/County:	Direction (facing):	State:
Location: Formosa Plastics Corp.		
Subject: No photo; Logbook mis-numbered		
Photo ID:		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 83

No Photograph

Photographer:	Date:	Time:
City/County:	Direction (facing):	State:
Location: Formosa Plastics Corp.		
Subject: No photo; Logbook mis-numbered		
Photo ID:		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 84

No Photograph

Photographer:	Date:	Time:
City/County:	Direction (facing):	State:
Location: Formosa Plastics Corp.		
Subject: No photo; Logbook mis-numbered		
Photo ID:		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 85

No Photograph

Photographer:	Date:	Time:
City/County:	Direction (facing):	State:
Location: Formosa Plastics Corp.		
Subject: No photo; Logbook mis-numbered		
Photo ID:		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 86

No Photograph

Photographer:	Date:	Time:
City/County:	Direction (facing):	State:
Location: Formosa Plastics Corp.		
Subject: No photo; Logbook mis-numbered		
Photo ID:		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log

Photo No. 87

No Photograph

Photographer:	Date:	Time:
City/County:	Direction (facing):	State:
Location: Formosa Plastics Corp.		
Subject: No photo; Logbook mis-numbered		
Photo ID:		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 88

No Photograph

Photographer:	Date:	Time:
City/County:	Direction (facing):	State:
Location: Formosa Plastics Corp.		
Subject: No photo; Logbook mis-numbered		
Photo ID:		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 89

No Photograph

Photographer:	Date:	Time:
City/County:	Direction (facing):	State:
Location: Formosa Plastics Corp.		
Subject: No photo; Logbook mis-numbered		
Photo ID:		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 90



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 2:34 PM
City/County: Point Comfort, Calhoun	Direction (facing): Down	State: TX
Location: Formosa Plastics Corp.		
Subject: Outfall 006 - Close-up of plastic pellets on concrete steps from earlier highwater event downstream of gate		
Photo ID: DSCF3409		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 91



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 2:35 PM
City/County: Point Comfort, Calhoun	Direction (facing): Down	State: TX
Location: Formosa Plastics Corp.		
Subject: Outfall 006 - Close-up of plastic pellets showing various sizes, shapes and forms of plastic residue (white fluff) (see Photo 92)		
Photo ID: DSCF3410		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 92



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 2:35 PM
City/County: Point Comfort, Calhoun	Direction (facing): Down	State: TX
Location: Formosa Plastics Corp.		
Subject: Outfall 006 - Close-up of plastic pellets showing various sizes, shapes and forms of plastic residue (white fluff) (see Photo 91)		
Photo ID: DSCF3411		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 93



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 2:36 PM
City/County: Point Comfort, Calhoun	Direction (facing): West	State: TX
Location: Formosa Plastics Corp.		
Subject: Outfall 006 - Screen at outfall 006 showing apparent clog of plant matter and plastic debris		
Photo ID: DSCF3412		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 94



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 2:37 PM
City/County: Point Comfort, Calhoun	Direction (facing): Down	State: TX
Location: Formosa Plastics Corp.		
Subject: Outfall 006 - Pellets floating on creek-side and beyond the concrete apron of of Outfall 006, flowing towards Cox Creek		
Photo ID: DSCF3413		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log

Photo No. 95



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 2:40 PM
City/County: Point Comfort, Calhoun	Direction (facing): Northeast	State: TX
Location: Formosa Plastics Corp.		
Subject: Outfall 007		
Photo ID: DSCF3414		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 96



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 2:41 PM
City/County: Point Comfort, Calhoun	Direction (facing): Down	State: TX
Location: Formosa Plastics Corp.		
Subject: Outfall 007 - Screen downstream of gate		
Photo ID: DSCF3415		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 97



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 2:55 PM
City/County: Point Comfort, Calhoun	Direction (facing): South	State: TX
Location: Formosa Plastics Corp.		
Subject: Soil Staging Pile - Soil staging pile located in far northeast quadrant of FPC, new SVCP plant in background		
Photo ID: DSCF3416		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 98



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 2:55 PM
City/County: Point Comfort, Calhoun	Direction (facing): North	State: TX
Location: Formosa Plastics Corp.		
Subject: Soil Staging Pile - Apparent staging area for excavated soil from new SPVC construction site; visible on Google photographs		
Photo ID: DSCF3417		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 99



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 3:09 PM
City/County: Point Comfort, Calhoun	Direction (facing): West	State: TX
Location: Formosa Plastics Corp.		
Subject: Outfall 008 - Ethylene glycol and polypropylene plants in the background (see Photo 100)		
Photo ID: DSCF3418		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 100



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 3:09 PM
City/County: Point Comfort, Calhoun	Direction (facing): East	State: TX
Location: Formosa Plastics Corp.		
Subject: Outfall 008 (see Photo 99)		
Photo ID: DSCF3419		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log

Photo No. 101



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 3:11 PM
City/County: Point Comfort, Calhoun	Direction (facing): Down	State: TX
Location: Formosa Plastics Corp.		
Subject: Outfall 008 - Apparent deposit of plastic pellets on concrete apron from previous high water event		
Photo ID: DSCF3420		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 102



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 3:11 PM
City/County: Point Comfort, Calhoun	Direction (facing): Down	State: TX
Location: Formosa Plastics Corp.		
Subject: Outfall 008 - Close-up of apparent deposit of plastic pellets on concrete apron from previous high water event		
Photo ID: DSCF3421		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 103



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 3:11 PM
City/County: Point Comfort, Calhoun	Direction (facing): Down	State: TX
Location: Formosa Plastics Corp.		
Subject: Outfall 008 - Close-up of plastic pellets of different shapes and sizes (see Photos 104 and 105)		
Photo ID: DSCF3422		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 104



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 3:12 PM
City/County: Point Comfort, Calhoun	Direction (facing): Down	State: TX
Location: Formosa Plastics Corp.		
Subject: Outfall 008 - Close-up of plastic pellets of different shapes and sizes (see Photos 103 and 105)		
Photo ID: DSCF3423		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 105



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 3:13 PM
City/County: Point Comfort, Calhoun	Direction (facing): Down	State: TX
Location: Formosa Plastics Corp.		
Subject: Outfall 008 - Close-up of plastic pellets of different shapes and sizes (see Photos 103 and 104)		
Photo ID: DSCF3424		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 106



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 3:19 PM
City/County: Point Comfort, Calhoun	Direction (facing): Down	State: TX
Location: Formosa Plastics Corp.		
Subject: Outfall 008 - Feral hog prints in mud downstream from Outfall 008 before the drainage crosses through chain-link fence on east side of property		
Photo ID: DSCF3425		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 107



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 3:20 PM
City/County: Point Comfort, Calhoun	Direction (facing): Down	State: TX
Location: Formosa Plastics Corp.		
Subject: Outfall 008 - Plastic pellets downstream of Outfall 008		
Photo ID: DSCF3426		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 108



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 3:21 PM
City/County: Point Comfort, Calhoun	Direction (facing): East	State: TX
Location: Formosa Plastics Corp.		
Subject: Outfall 008 - Facing east from Outfall 006 [sic, this should be 008]		
Photo ID: DSCF3427		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log

Photo No. 109



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 3:25 PM
City/County: Point Comfort, Calhoun	Direction (facing): South	State: TX
Location: Formosa Plastics Corp.		
Subject: Outfall 008 - Soil staging pile near outfall 006 [sic, this should be 008]		
Photo ID: DSCF3428		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log

Photo No. 110



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 3:25 PM
City/County: Point Comfort, Calhoun	Direction (facing): Northeast	State: TX
Location: Formosa Plastics Corp.		
Subject: Railcar Repair and Maintenance Facility - Stack of creosote timbers on ground		
Photo ID: DSCF3429		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log

Photo No. 111



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 3:27 PM
City/County: Point Comfort, Calhoun	Direction (facing): Northwest	State: TX
Location: Formosa Plastics Corp.		
Subject: Railcar Repair and Maintenance Facility - New creosote timbers on ground and metal parts and railroad spikes in drums; Maintenance building in background		
Photo ID: DSCF3430		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 112



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 3:28 PM
City/County: Point Comfort, Calhoun	Direction (facing): Down	State: TX
Location: Formosa Plastics Corp.		
Subject: Railcar Repair and Maintenance Facility - Scrap metals inside red roll-off box that was not tarpred or closed at the time of the inspection		
Photo ID: DSCF3431		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log

Photo No. 113



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 3:30 PM
City/County: Point Comfort, Calhoun	Direction (facing): West	State: TX
Location: Formosa Plastics Corp.		
Subject: Railcar Repair and Maintenance Facility - New creosote timbers in laydown storage area		
Photo ID: DSCF3432		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log

Photo No. 114



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 3:32 PM
City/County: Point Comfort, Calhoun	Direction (facing): West	State: TX
Location: Formosa Plastics Corp.		
Subject: Railcar Repair and Maintenance Facility - Corroded red container (boxcar) marked with "oily rags only" near Maintenance Facility		
Photo ID: DSCF3433		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 115



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 3:34 PM
City/County: Point Comfort, Calhoun	Direction (facing): Northwest	State: TX
Location: Formosa Plastics Corp.		
Subject: Railcar Repair and Maintenance Facility - Polypropylene facility in background (Verhalen - EPA)		
Photo ID: DSCF3434		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 116



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 3:53 PM
City/County: Point Comfort, Calhoun	Direction (facing): Southwest	State: TX
Location: Formosa Plastics Corp.		
Subject: Railcar Repair and Maintenance Facility - Inside maintenance bay; damage to top of railcar (Verhalen - EPA, FPC personnel)		
Photo ID: DSCF3435		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log

Photo No. 117



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 3:58 PM
City/County: Point Comfort, Calhoun	Direction (facing): Northeast	State: TX
Location: Formosa Plastics Corp.		
Subject: Railcar Repair and Maintenance Facility - Drums of solid asphalt in equipment storage yard (Verhalen - EPA). (NOTE: Drums were appropriately covered prior to photo.)		
Photo ID: DSCF3436		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 118



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 4:04 PM
City/County: Point Comfort, Calhoun	Direction (facing): Northwest	State: TX
Location: Formosa Plastics Corp.		
Subject: Outfall 009		
Photo ID: DSCF3437		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 119



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 4:045 PM
City/County: Point Comfort, Calhoun	Direction (facing): Down	State: TX
Location: Formosa Plastics Corp.		
Subject: Outfall 009 - Plastic pellets (see Photo 120)		
Photo ID: DSCF3438		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 120



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 4:05 PM
City/County: Point Comfort, Calhoun	Direction (facing): Down	State: TX
Location: Formosa Plastics Corp.		
Subject: Outfall 009 - Plastic pellets (see Photo 119)		
Photo ID: DSCF3439		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log

Photo No. 121



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 4:17 PM
City/County: Point Comfort, Calhoun	Direction (facing): Northwest	State: TX
Location: Formosa Plastics Corp.		
Subject: Outfall 006 - Soil staging piles with what appears to be black plastic sticking out (see Photos 122 and 123)		
Photo ID: DSCF3440		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 122



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 4:18 PM
City/County: Point Comfort, Calhoun	Direction (facing): North	State: TX
Location: Formosa Plastics Corp.		
Subject: Outfall 006 - Soil staging piles with what appears to be black plastic sticking out (see Photos 121 and 123)		
Photo ID: DSCF3441		

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Official Photograph Log
Photo No. 123



Photographer: Nancy Fagan	Date: 6/16/2010	Time: 4:18 PM
City/County: Point Comfort, Calhoun	Direction (facing): Northeast	State: TX
Location: Formosa Plastics Corp.		
Subject: Outfall 006 - Soil staging piles with what appears to be black plastic sticking out (see Photos 121 and 122)		
Photo ID: DSCF3442		

END OF PHOTOGRAPHS
June 16, 2010

